

Skokie Park District
ADA Evaluation and Transition Plan Update
March 18, 2025

The Skokie Park District has made steady progress with the Americans with Disabilities Act (ADA) transition plan over the past thirteen years. With a high number of park improvements and facility changes over the past 13 years, a new audit will be performed during the 2025/26 FY. Funds have been allocated for this to be performed by a contractor that specializes in audits of this type and sites that have undergone significant changes will be the primary focus.

The following items below have been updated to comply with ADA for playgrounds and facilities over the past year. Please see the attached spreadsheets for more details.

This year a major renovation was completed at Reid Park and several accessibility issues were addressed. The items brought into compliance are as follows: the asphalt path around the park was removed and replaced with concrete, the sand play surfacing within the playground was removed and replaced with engineered wood fiber, new play equipment with ground play features and accessible transition decks were installed, concrete ramps providing access into the playground were installed, new swings which included a plastic molded swing with harness was installed, and new accessible benches and picnic tables were installed throughout the park.

A playground renovation was also completed at Pawnee Park which included the installation of play equipment with accessible features and new accessible benches and picnic tables. The brick pad where the picnic tables had been located was removed and replaced with a concrete pad.

The asphalt path at Gross Point was milled and repaved, which repaired cracks and shifting due to the age of the path.

The Commemorative Bench program launched in 2020, and any new bench/pad combos include both an accessible bench and accessible pad. New commemorative bench pads and/or accessible benches were installed at Oakton Park and Devonshire Park.

Engineered wood fiber (EWF) was added to the following playground sites which kept them in compliance with ADA access: Hamlin, Laramie, Playtime, Reid, Shack, and TLC where the play surfacing on both the east and west side was completely removed and replaced.

Report prepared by:
Corrie Guynn-Superintendent of Parks, Planning and Facilities
March 18, 2025



ADA Transition Plan Annual Update: FACILITIES

March 18, 2025

Facility	Room/Location	Feature	Barrier	Target Complete Date	Completed Date	Comments
Dammrich Rowing Ctr	Front entrance	Door (exterior)	Door is not accessible- requires excessive force	2023	2023	The damaged front door was replaced and is now much easier to open.
Dammrich Rowing Ctr	Walk way	Concrete	Eliminateed uneven cracks	2017	2017	Replaced and eliminated Architectural barriers
Dammrich Rowing Ctr	Hallway	Elevator	Elevator is not working	2013	2014	Elevator was repaired
Devonshire Aqu Ctr	Concession Area	Picnic Tables	Picnic tables are not handicapped accessible	2015	2015	Replaced one table to be accessible
Devonshire Aqu Ctr	Concession Area	Concession counter	Counter does not allow knee and space appropriate for individual in wheelchair	2025		Install appropriate counter or drop down accessible counter, future renovation project
Devonshire Aqu Ctr	Bathroom Building	Water Fountains	Water fountain does not allow free space for knee and toe clearance	2026		Lower or replace the existing drinking fountain, future renovation project
Devonshire Aqu Ctr	Main Pool	Pools	Refer to the ADA Evaluation Document for full description	2012	2013	Purchased and installed a portable pool lift
Devonshire Aqu Ctr	Women's 2nd locker room	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Devonshire Aqu Ctr	Men's 1st locker room	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Devonshire Aqu Ctr	Men's 2nd locker room	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Devonshire Cultural Ctr	Front entrance	Door (exterior)	South door is not accessible	2013	2014	Completed
Devonshire Cultural Ctr	East entrance	Door (exterior)	Automatic doors not working, switch not turned on	2011	2011	Trained staff on importance of making sure the switch is turned on daily
Devonshire Cultural Ctr	Front Walk	Poured new walk	Eliminated uneven sections	2016	2016	Completed Fall of 2016
Devonshire Cultural Ctr	East Parking lot	ADA Curb depression	Remove and replace a section for ADA access	2016	2016	Completed Fall of 2016
Devonshire Cultural Ctr	Women's restroom, 2nd flr	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Devonshire Cultural Ctr	??	Garbage can	Garbage can at entrance does not allow proper maneuvering clearance	2011	2012	Moved garbage can to other side to allow proper clearance for a wheelchair to enter
Devonshire Cultural Ctr	Men's restroom, 2nd flr	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Devonshire Cultural Ctr	Room 113	Sink	Exposed pipes and wires	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn



ADA Transition Plan Annual Update: FACILITIES

March 18, 2025

Facility	Room/Location	Feature	Barrier	Target Complete Date	Completed Date	Comments
Devonshire Cultural Ctr	Room 112	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Devonshire Cultural Ctr	Room 111	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Devonshire Cultural Ctr	Room 105	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Devonshire Cultural Ctr	Room 106	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Devonshire Cultural Ctr	Hallway, 2nd Floor	Drinking Fountain	Water flow not high enough	2011	2013	Increased flow of water from fountains upstairs
Devonshire Cultural Ctr	Theatre	Stage	No access for individual in wheelchair	2011	2012	Trained staff to know location of lift at all times
Emily Oaks Nature Ctr	Front Entrance	Door (exterior)	Automatic doors not working properly	2011	2012	Repaired doors
Oakton Community Ctr	Exploritorium, family restroom	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Oakton Community Ctr	Room #115	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Oakton Community Ctr	Exploritorium	Stage	Access to stage for individual in wheelchair	2011	2011	Rebuilt stage on grade
Oakton Community Ctr	Exploritorium	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Oakton Community Ctr	Entrances, East & West	Concrete	Jacked to eliminate uneven surface	2017	2017	Raised to eliminate Architectural barriers.
Oakton Community Ctr	Exploritorium, front desk	Counter	Counter did not allow knee and space appropriate for individual in wheelchair	2010	2010	Made counter accessible
Skokie Heritage Museum	First Floor	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Skokie Heritage Museum	Second Floor	Sink	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Skokie Heritage Museum	Log cabin	Ramp	Lip in base of cement wooden ramp	2012	2012	Provided flat, even accessible route
Skokie Water Playground	Party Area	Accessible Routes/Walks	Sidewalk has sunk creating a change in level in excess of 0.25"	2020	2020	Sidewalk grinder was used to repair
Skokie Water Playground	Concession/Party Area	Picnic Tables	Picnic tables are not handicapped accessible	2015	2015	Replaced one table to be handicapped accessible.
Skokie Water Playground	Concession Area	Concession counter	Counter does not allow knee and space appropriate for individual in wheelchair	2025		Install appropriate counter or drop down accessible counter, future renovation project



ADA Transition Plan Annual Update: FACILITIES

March 18, 2025

Facility	Room/Location	Feature	Barrier	Target Complete Date	Completed Date	Comments
Skokie Water Playground	Main Pool	Pools	Refer to the ADA Evaluation Document for full description	2012	2013	Purchased and installed a portable lift and portable stairs
Skokie Water Playground	Women's Locker Room	Sink, 1st	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Skokie Water Playground	Women's Locker Room	Sink, 2nd	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Skokie Water Playground	Men's Locker Room	Sink, 1st	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Skokie Water Playground	Men's Locker Room	Sink, 2nd	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Skatium	Skatium Men's restroom	Sinks, left and right side	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Skatium	Skatium Women's restroom	Sinks, Left, middle & right side	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Skatium	Skatium	Doors to ice rink	Doors require excess force to open	2011	2011	Installed doors requiring less force to open
Sports Park	Various areas	Sidewalks	Walks with lips greater than .25"	2020	2020	Ground raised areas to remove barrier
Tot Learning Center	Entrance Walk	Accessible Routes/Walks	Concrete walk has settled behind curb.	2014	2014	Concrete jacked flush with back of curb
WLC	Second Floor, Women's Restroom	Sink, left side	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
WLC	Second Floor, Men's Restroom	Sink, left side	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
WLC	First Floor, Women's East side restroom	Sink, right side	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
WLC	First Floor, Men's East side restroom	Sink, left side	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
WLC	Fitness First , Women's locker room	Shower	No grab bars installed for transfer type shower	2011	2012	Installed grab bars
WLC	Fitness First	Drinking Fountain, east	Doesn't allow enough free space for knee and toe clearance	2011	2011	Found an alternate location for 2 chairs next to fountain in order to allow proper clear floor space and knee and toe clearance for wheelchair and walker use.
WLC	Fitness First	Drinking Fountain, WEST	Doesn't allow enough free space for knee and toe clearance	2011	2011	Found an alternate location for 2 chairs next to fountain in order to allow proper clear floor space and knee and toe clearance for wheelchair and walker use.



ADA Transition Plan Annual Update: FACILITIES

March 18, 2025

Facility	Room/Location	Feature	Barrier	Target Complete Date	Completed Date	Comments
WLC	Fitness First	Men's and Women's whirlpools	Insufficient space to provide patron lift for access to whirlpool.	2017	2017	Converted to steam rooms during 2016 renovations
WLC	Front Desk	Side Counter	Counter does not allow knee and space appropriate for individual in wheelchair	2017	2017	Completed during 2017 renovations
WLC	Gym Desk	Counter	Counter does not allow knee and space appropriate for individual in wheelchair	2012	2012	Installed drop down accessible counter. Removed
Miscellaneous		Agency Mission	Agency mission does not specifically include a belief statement about inclusion of people with disabilities	2019	2019	Inclusivity added as a core value.
Miscellaneous		Agency Communications	Alternative forms of communications has not been a priority	2019		Review alternative forms of communications and determine forms that can be utilized and implemented.



ADA Transition Plan Annual Update: PARKS

3/18/2025

Park	Location	Feature	Barrier	Target Complete Date	Completed Date	Comments
Carol Park	Swing area	Ramps	No accessible ramp into swing ramp	2021	2021	Provided accessible ramp into area
Carol Park	All	Surface	Does not provide access to all playground equipment	2021	2021	Completed as part of the park renovation
Carol Park	Swing area	Transfer Points	Non-accessible sand playground surfacing. No transfer system. No accessible ramp into swing area.	2021	2021	Completed as part of the park renovation
Carol Park	All	Benches	No arm rests for transferring from wheelchair	2011	2012	Added an arm rest to one of the benches
Central Park	Picnic area	Accessible Routes/Walks	No accessible routes to picnic area	2014	2013	Added two ADA walks 2013
Central Park	Playground area	Ramps	Ramp accessing playground is in excess of 8.33%	2023	2023	Poured in place surfacing installed at ground level for the playground and ramp installed for swing area.
Central Park	Playground age group 5-12 group	Transfer Points	No transfer module	2023	2023	New playground equipment installed with transfer platforms.
Central Park	All	Benches	No arm rests for transferring from wheelchair	2011	2011	New benches added as part of park renovation.
Central Park	Picnic area	Picnic Tables	Picnic tables are not handicapped accessible	2017	2017	Concrete walkway poured
Channelside Park	Playground area	Ramps	Ramp accessing playground is in excess of 8.33%	2026		Replace ramp with accessible ramp during renovation
Channelside Park	Playground area	Transfer Points	Plus 10 Design, moderate access	2018		No changes contemplated
Channelside Park	All	Benches	No arm rests for transferring from wheelchair	2010	2012	Added an arm rest to one of the benches
Chippewa Park	Playground area	Surface	Non-accessible sand surfacing	2021	2019	Completed as part of the park renovation
Chippewa Park	Playground area	Transfer Points	Playground is not handicapped accessible	2021	2019	Completed as part of the park renovation
Chippewa Park	All	Benches	No arm rests for transferring from wheelchair	2010	2011	Completed as part of the park renovation
Chippewa Park	Picnic area	Picnic Tables	Picnic tables are not handicapped accessible	*2017	2019	New accessible table installed
Devonshire Park	Playground area	Parking	No HC accessible stall provided	2010	2010	Created one accessible parking stall with proper signage and striping
Devonshire Park	Basketball/Tennis area	Parking	Minimum number of accessible parking spaces	2011	2013	Added one accessible stall
Devonshire Park	Swing area	Accessible Routes/Walks	Does not allow accessibility to individual wheelchair	2011	2010	Completed as part of the park renovation
Devonshire Park	Entrance to play equip	Ramps	Lip in base of cement and ramp	2011	2011	Completed as part of the park renovation
Devonshire Park	Parking Lot	Ramp	Add an additional ramp by East Entrance	2013	2013	Additional ramp added, east entrance
Devonshire Park	Parking Lot	Suffield/ Parking lot depress.	Created additional ADA access point	2016	2016	Created an additional access point
Devonshire Park	Leading to Gazebo	Ramps	Asphalt has sunk	2011	2013	Replaced asphalt at board walk entrances
Devonshire Park	Playground area	Transfer Points	Non-accessible transfer points to some playground equipment	2011	2011	Completed as part of the park renovation
Devonshire Park	All	Benches (2)	No arm rests for transferring from wheelchair	2010	2010	Added an arm rest to two of the benches
Devonshire Park	Picnic area	Picnic Tables	Picnic tables are not handicapped accessible	2010	2011	Removed one bench on table near playground area
Devonshire Park	Boardwalk	Picnic Tables	Picnic tables are not handicapped accessible	2010	2014	Removed two benches on tables on boardwalk
Emerson Park	Playground area	Transfer Points	Limited access to transfer system	2011	2012	Completed as part of the park renovation
Emerson Park	All	Benches	No arm rests for transferring from wheelchair	2011	2011	Added an arm rest to two of the benches



ADA Transition Plan Annual Update: PARKS

3/18/2025

Park	Location	Feature	Barrier	Target Complete Date	Completed Date	Comments
Emerson Park	Picnic area	Accessible Routes/Walks	No accessible routes to picnic area	2014	2014	Provided accessible route to a minimum of 1 picnic tables
Emerson Park	Playground area	Ramps	Walk to playground from northwest has sunk creating a change in excess of 0.25"	2012	2012	Completed as part of the park renovation
Emily Oaks Nat Ctr	Playground area	Accessible Routes/Walks	No accessible entry point for individual to gain access to play equipment	2012	2012	Completed as part of the park renovation
Emily Oaks Nat Ctr	Sand area	Accessible Routes/Walks	No accessible route to sand area	2012	2012	Completed as part of the park renovation
Emily Oaks Nat Ctr	Picnic area	Accessible Routes/Walks	No accessible routes to picnic area	2012	2012	Completed as part of the park renovation
Emily Oaks Nat Ctr	All	Benches (2)	No arm rests for transferring from wheelchair	2010	2010	Added an arm rest to two of the benches
Emily Oaks Nat Ctr	Picnic area	Picnic Tables	Picnic tables are not handicapped accessible	2012	2012	Removed one seat from one picnic table to provide compliant tables with appropriate knee and toe clearance
Emily Oaks Nat Ctr	Walkway	Accessible Routes/Walks	Raised paved walks/paths	2018	2018	Raised path above woodland water.
George St Parkway	Walks	Accessible Routes/Walks (2)	No paths, thus no accessible routes			No changes contemplated
Gleiss Park	Picnic area	Accessible Routes/Walks	No accessible route to picnic area	2014	2014	Provided accessible route to a minimum of 1 picnic tables
Gleiss Park	Playground area	Ramps	No accessible ramp leading into 5-12 age structure	2027		To be done as part of future renovation project
Gleiss Park	Playground area	Transfer Points	No transfer points to provide access to playground	2027		To be done as part of future renovation project
Gleiss Park	All	Benches (2)	No arm rests for transferring from wheelchair	2010	2010	Added an arm rest to two of the benches
Gleiss Park	Picnic area	Picnic Tables	Picnic tables are not handicapped accessible	2018	2018	Removed one seat from one picnic table to provide compliant tables with appropriate knee and toe clearance by playground
Gross Point Park	Playground area	Surface	Does not provide access to all playground equipment	2021	2021	Completed as part of the park renovation
Gross Point Park	Playground area	Transfer Points	No transfer points to provide access to playground	2021	2021	Completed as part of the park renovation
Gross Point Park	All	Benches	No arm rests for transferring from wheelchair	2011	2012	Completed as part of the park renovation
Gross Point Park	Picnic area	Picnic Tables	Picnic tables are not handicapped accessible	2010	N/A	Completed as part of the park renovation
Hamlin Park	Playground area	Ramps	No accessible route into sand surface playground	2021	2021	Completed as part of the park renovation
Hamlin Park	Playground area	Surface	Does not provide access to all playground equipment	2021	2021	Completed as part of the park renovation
Hamlin Park	Playground area	Transfer Points	No transfer points to provide access to playground, sand based playground	2021	2021	Completed as part of the park renovation
Hamlin Park	All	Benches	No arm rests for transferring from wheelchair	2010	2011	Added an arm rest to one of the benches
Hamlin Park	Picnic area	Picnic Tables	Remove one bench for ADA access	2011	2011	One bench removed
Hamlin Park	Shelter	Sinks	Exposed pipes	2011	2013	Covered pipes completely to make sure hot pipes are not able to burn
Laramie Park	Playground area	Transfer Points	No transfer points to provide access to playground	2020	2020	Completed as part of the park renovation



ADA Transition Plan Annual Update: PARKS

3/18/2025

Park	Location	Feature	Barrier	Target Complete Date	Completed Date	Comments
Laramie Park	Playground area	Surface	Does not provide access to all playground equipment	2020	2020	Completed as part of the park renovation
Laramie Park	Sidewalk	Jacking walk way	Uneven walk joints	2017	2017	Lifted walk
Laramie Park	All	Benches	No arm rests for transferring from wheelchair	2011	2012	Add one arm rest to three benches
Laramie Park	Picnic area	Picnic Tables	Picnic tables are not handicapped accessible	2011	2012	Removed one seat from two picnic tables to provide compliant tables with appropriate knee and toe clearance
Lauth Park	Curb/Swing area	Accessible Routes/Walks	No curb and No accessible route to swing area	2025		Cut a handicap depressed in curb line. Provide accessible route to swing area. To be done as part of future renovation project
Lauth Park	Playground area	Transfer Points	No transfer points to provide access to playground	2025		To be done as part of future renovation project
Lauth Park	All	Benches	No arm rests for transferring from wheelchair	2011	2012	Added an arm rest to one of the benches
Reid (Lawler) Park	Asphalt paths	Accessible Routes/Walks	Asphalt pathways have numerous cracks and uneven surfaces	2024	2024	Paths repaved as concrete during renovation.
Reid (Lawler) Park	Picnic area	Accessible Routes/Walks	No accessible route to picnic area	2012	2012	Accessible route to a minimum of 2 picnic tables exists by playground
Reid (Lawler) Park	Playground area	Ramps	No accessible route into sand surface play equipment	2024	2024	Completed during renovation.
Reid (Lawler) Park	Playground area	Transfer Points	No transfer points to provide access to playground	2024	2024	Completed during renovation.
Reid (Lawler) Park	All	Benches	No arm rests for transferring from wheelchair	2012	2012	Completed during renovation.
Lee Wright Park	All	Benches	No arm rests for transferring from wheelchair	2011	2012	Added an arm rest to one of the benches
Lee Wright Park	Playground area	Ramps	No accessible ramp into playground surface	2011	2011	Added an ADA accessible ramp into area exists.
Lockwood Park	All	Benches	No arm rests for transferring from wheelchair	2012	2011	Added an arm rest to three of the benches
Lockwood Park	All	Picnic Tables	Picnic tables are not handicapped accessible	2020	2020	Added accessible table to west on concrete
Lorel Park	Sidewalks	Accessible Routes/Walks	Sidewalk has sunk creating a change in level. Infield mix has washed onto sunken sidewalk	2010	2010	Sidewalk repaired. Infield mix removed.
Lorel Park	Curbs	Accessible Routes/Walks	No curb cut	2023	2015	Village has installed sidewalk curb cuts
Lorel Park	Ball diamond	Accessible Routes/Walks	Athletic box blocks the accessible route	2011	2011	Found a different location for the athletic box
Lorel Park	Village sidewalk	Accessible Routes/Walks	Sunk creating a change in level	2022	2022	Completed as part of the park renovation
Lorel Park	Asphalt paths	Accessible Routes/Walks	Asphalt sidewalk has sunk creating a change in level	2022	2022	Completed as part of the park renovation
Lorel Park	Picnic area	Accessible Routes/Walks	No accessible route to picnic area	2014	2014	Completed as part of the park renovation
Lorel Park	Playground area	Transfer Points	No transfer points to provide access to playground	2022	2022	Completed as part of the park renovation
Lorel Park	All	Benches	No arm rests for transferring from wheelchair	2011	2011	Added an arm rest to one of the three benches
Lorel Park	Picnic area	Picnic Tables	Picnic tables are not handicapped accessible	2011	2014	Removed one seat from 2 picnic tables to provide compliant tables with appropriate knee and toe clearance
Lorel Park	Tennis court area	Park Site	Surfacing of court is very poor	2013	2014	Resurfaced tennis court



ADA Transition Plan Annual Update: PARKS

3/18/2025

Park	Location	Feature	Barrier	Target Complete Date	Completed Date	Comments
Lorel Park	Washrooms	Shelter	Men's-Door requires too much force to open to be handicap accessible, the urinal stall too narrow, the sink stall is too narrow, the sink has piping that is exposed. Women's -Barely 36" width for the passage, hand dryer in the way that reduced that and sink stall is too narrow	2027		To be done as part of future renovation project. Major renovation of shelter building would be needed. Partitions were reconfigured in 2021 to allow for more space within the building.
Lyon Park	All	Benches	No arm rests for transferring from wheelchair	2011	2011	Added two arm rests to benches (1 in pg & 1 other)
Lyon Park	Picnic area	Picnic Tables	Picnic tables are not handicapped accessible	2020	2020	Removed one seat from one picnic table to provide compliant tables with appropriate knee and toe clearance. New table installed.
Main Hamlin Tennis Complex	Near drinking fountain	Accessible Routes/Walks	Sidewalk has sunk creating a change in level	2021	2021	Replaced with new water fountain
Main Hamlin Tennis Complex	All	Benches	No arm rests for transferring from wheelchair	2011	2011	Added an arm rest to one of the benches
McNally Park	Playground	Surface	Create handicap accessibility	2015	2015	Completed renovation of playground
McNally Park	Picnic area	Accessible Routes/Walks	Sidewalk not curb cut at southeast corner	2027		This sidewalk is VOS property. Will need to work with Village to have completed.
McNally Park	All	Benches	No arm rests for transferring from wheelchair	2012	2012	Added an arm rest to one of the benches
McNally Park	Picnic area, bleacher	Picnic Tables	Picnic tables are not handicapped accessible	2020	2020	Removed one seat from one picnic table to provide compliant tables with appropriate knee and toe clearance. Provided accessible area near public seating areas
Menominee Park	Playground area	Playground Equipment	Not accessible	2022	2022	Completed as part of the park renovation
Menominee Park	Playground area	Ramps	No accessible ramp into playground surface	2022	2022	Completed as part of the park renovation
Menominee Park	Playground area	Transfer Points	No transfer points to provide access to playground	2022	2022	Completed as part of the park renovation
Menominee Park	All	Benches	No arm rests for transferring from wheelchair	2012	2011	Added an arm rest to one of the benches
Mulford Park	Playground area	Playground Equipment	No ADA accessible components	2019	2019	Completed as part of the park renovation
Mulford Park	Playground area	Ramps	No accessible ramp into playground surface	2021	2019	Completed as part of the park renovation
Mulford Park	Playground area	Surface	Non-accessible sand surfacing	2019	2019	Completed as part of the park renovation
Mulford Park	Playground area	Transfer Points	No transfer points to provide access to playground	2019	2019	Completed as part of the park renovation
Mulford Park	All	Benches	No arm rests for transferring from wheelchair	2012	2011	Added an arm rest to one of the benches
Navajo Park	Playground area	Playground Equipment	Not accessible	2021	2021	Completed as part of the park renovation
Navajo Park	Playground area	Ramps	No accessible ramp into playground surface	2021	2021	Completed as part of the park renovation
Navajo Park	Playground area	Surface	Non-accessible sand surfacing	2021	2021	Completed as part of the park renovation
Navajo Park	Playground area	Transfer Points	No transfer points to provide access to playground	2021	2021	Completed as part of the park renovation
Navajo Park	All	Benches	No arm rests for transferring from wheelchair	2012	2012	Completed as part of the park renovation



ADA Transition Plan Annual Update: PARKS

3/18/2025

Park	Location	Feature	Barrier	Target Complete Date	Completed Date	Comments
Oakton Park	Playground area	Playground Equipment	Not accessible	2010	2010	Completed as part of the park renovation
Oakton Park	Playground area	Ramps	No accessible ramp into playground surface	2010	2010	Completed as part of the park renovation
Oakton Park	Playground area	Surface	Non-accessible sand surfacing	2010	2010	Completed as part of the park renovation
Oakton Park	Playground area	Transfer Points	No transfer points to provide access to playground	2010	2010	Completed as part of the park renovation
Oakton Park	Playground area	Accessible Routes/Walks	Not accessible	2010	2010	Completed as part of the park renovation
Oakton Park	All	Benches (3)	No arm rests for transferring from wheelchair	2010	2010	Added an arm rest to three of the benches
Oakton Park	Picnic area	Picnic Tables		2010	2010	Completed as part of the park renovation
Oakton Park	Near tennis court	Drinking Fountain		2010	2010	Completed as part of the park renovation
Oakton Park	Near diamonds	Shelter	Sink, exposed pipes	2011	2011	Covered with foam
Pawnee Park	Playground area	Ramps	No accessible ramp into playground surface	2023	2023	There are existing ramps to both play areas
Pawnee Park	All	Benches (1)	No arm rests for transferring from wheelchair	2012	2010	Added an arm rest to one of the benches
Peccia Park	All	Accessible Routes/Walks	Some sidewalks with excession gaps	2013	2012	Repaired walks
Peccia Park	Playground area	Playground Equipment	Not accessible	2021	2021	Completed as part of the park renovation
Peccia Park	Playground area	Ramps	No accessible ramp into playground surface	2021	2021	Completed as part of the park renovation
Peccia Park	Playground area	Surface	Non-accessible sand surfacing	2021	2021	Completed as part of the park renovation
Peccia Park	Playground area	Transfer Points	No transfer points to provide access to playground	2021	2021	Completed as part of the park renovation
Peccia Park	All	Benches	No arm rests for transferring from wheelchair	2012	2012	Completed as part of the park renovation
Peccia Park	Sidewalk	Jacking walk way	Uneven walk joints	2016	2016	Completed as part of the park renovation
Playtime Park	All	Accessible Routes/Walks	Sidewalks damaged with excess gaps or heaving. Gate access not accessible.	2021	2021	Replaced select sidewalk sections
Playtime Park	All	Ramps	Not accessible	2021	2021	Completed as part of the park renovation
Playtime Park	Playground area	Transfer Points	Not accessible	2021	2021	Completed as part of the park renovation
Playtime Park	All	Benches	No arm rests for transferring from wheelchair	2012	2011	Added an arm rest to one of the benches
Pohatan Park	Playground area	Playground Equipment	Not accessible, only one ADA digger	2021	2021	Completed as part of the park renovation
Pohatan Park	Playground area	Surface	Non accessible playground surface	2021	2021	Completed as part of the park renovation
Pohatan Park	Playground area	Transfer Points	No transfer points to provide access to playground	2021	2021	Completed as part of the park renovation
Pohatan Park	All	Benches	No arm rests for transferring from wheelchair	2012	2012	Completed as part of the park renovation
Pohatan Park	Picnic area	Picnic Tables	Picnic tables are not handicapped accessible	2021	2021	Tables were removed and replaced with benches.
Schack Park	Playground area	Ramps	No accessible ramp into playground surface	2018	2018	Completed as part of the park renovation
Schack Park	Playground area	Surface	Non-accessible sand surfacing	2018	2018	Completed as part of the park renovation
Schack Park	Playground area	Transfer Points	No transfer points to provide access to playground	2018	2018	Completed as part of the park renovation
Schack Park	All	Benches	No arm rests for transferring from wheelchair	2013	2011	Completed as part of the park renovation
Schack Park	Picnic area	Picnic Tables	Picnic tables are not handicapped accessible	2013	2013	Added two ADA walks 2013



ADA Transition Plan Annual Update: PARKS

3/18/2025

Park	Location	Feature	Barrier	Target Complete Date	Completed Date	Comments
Schack Park	All	Water Fountain	Leaking underneath where foot and knee clearance should be for individual in wheelchair	2011	2011	Completed as part of the park renovation
Schack Park	Sidewalk	Jacking walk way	Uneven walk joints	2017	2017	Completed as part of the park renovation
Schack Park	Sidewalk	Jacking walk way	Uneven walk joints	2016	2016	Completed as part of the park renovation
Seneca Park	All	Benches	No arm rests for transferring from wheelchair	2011	2012	Added an arm rest to one of the benches
Sequoia Park	Playground area	Surface	Non accessible playground surface	2010	2010	Completed as part of the park renovation
Sequoia Park	Playground area	Transfer Points	No transfer points to provide access to playground	2010	2010	Completed as part of the park renovation
Sequoia Park	Sidewalk	Walk repairs	Uneven walk joints	2018	2018	Repaired walk
Sequoia Park	All	Benches	No arm rests for transferring from wheelchair	2011	2012	Added an arm rest to one of the benches
Shabonee Park	Playground area	Accessible Routes/Walks	No accessible route	2021	2021	Completed as part of the park renovation
Shabonee Park	Playground area	Ramps	Long ramp into playground exists	2021	2021	Completed as part of the park renovation
Shabonee Park	Playground area	Transfer Points	No transfer points to provide access to playground	2021	2021	Completed as part of the park renovation
Shabonee Park	All	Benches	No arm rests for transferring from wheelchair	2011	2012	Completed as part of the park renovation
Shawnee Park	Basketball court area	Accessible Routes/Walks	Lip at base of cement south of bball court, trip hazzard	2011	2011	Repaired walk
Shawnee Park	Playground area	Playground Equipment	No transfer point for wheelchair	2027		Possibly install grab bar - Future major renovation
Shawnee Park	Playground area	Ramps	Railing does not conform	2027		Future playground renovation- price out modification
Shawnee Park	All	Benches	No arm rests for transferring from wheelchair	2013	2011	Added an arm rest to one of the benches
Skokie Park Tennis Center	Garden plots	Accessible Routes/Walks	No accessible routes to garden plots	2024	2024	Accessible garden plots completed in 2024.
Skokie Park Tennis Center	All	Benches	No arm rests for transferring from wheelchair	2013	2011	Added an arm rest to one of the benches
Tecumseh Park	Playground area	Playground Equipment	Not accessible	2021	2021	Completed as part of the park renovation
Tecumseh Park	Playground area	Ramps	No accessible ramp into playground surface	2021	2021	Completed as part of the park renovation
Tecumseh Park	Playground area	Surface	Non-accessible sand surfacing	2021	2021	Completed as part of the park renovation
Tecumseh Park	Playground area	Transfer Points	No transfer points to provide access to playground	2021	2021	Completed as part of the park renovation
Tecumseh Park	All	Benches	No arm rests for transferring from wheelchair	2013	2011	Completed as part of the park renovation
Tecumseh Park	Sidewalk	Jacking walk way	Uneven walk joints	2016	2016	Lifted walk
Terminal Park	All	Accessible Routes/Walks	Gaps and heaving sections of accessible routes	2015	2014	Repaired walk
Terminal Park	Kolmar/Emerson	Accessible Routes/Walks	Curb cut has detectable warning but no color	2025		Paint from curbside to cross walk
Terminal Park	Swing area	Transfer Points	No access to swing area from bench/picnic area	2025		Provide accessible ramp into area in future renovation
Terminal Park	All	Benches	No arm rests for transferring from wheelchair	2014	2012	Added an arm rest to one of the benches
Timber Ridge Park	Asphalt paths	Accessible Routes/Walks	Asphalt path is rough with gaps and heaving	2016	2016	Repaired asphalt path
Timber Ridge Park	All	Benches (1)	No arm rests for transferring from wheelchair	2010	2010	Added an arm rest to one of the benches



ADA Transition Plan Annual Update: PARKS

3/18/2025

Park	Location	Feature	Barrier	Target Complete Date	Completed Date	Comments
Timber Ridge Park	Playground area	Playground Equipment	Accessible surface and Structure	2014	2016	Accessible Playground installed and EWF surface
Veterans Park	Sidewalk	Jacking Walk way	Uneven walk joints	2017	2017	Lifted walk
Weissburg Park	All	Accessible Routes/Walks	Path surfaces are uneven, excess crack with, curb ramp not accessible	2010	2011	Repaired walk
Weissburg Park	All	Benches	No arm rests for transferring from wheelchair	2013	2011	Added an arm rest to one of the benches
Winnebago Park	Playground area	Surface	Non-accessible sand surfacing	2017	2017	Completed as part of the park renovation
Winnebago Park	Playground area	Transfer Points	No transfer points on 5-12 age group structure	2017	2017	Completed as part of the park renovation
Winnebago Park	All	Benches	No arm rests for transferring from wheelchair	2011	2011	Added an arm rest to one of the benches